<b>Work Order ID 71071</b> <i>Monday, June 27, 2011 1:55:50 PM</i>			<u> </u>									Page		
Item ID: Revision ID: Item Name:	D3446-13 Right Buckle	Harness			A	ccept					Setup	Start Stop		
Start Date: Required Date: Reference:	6/21/2011 6/22/2011	Start Qty Req'd Qt	y: 1.00				Cust Ite Customo		DAR001					
Approvals:	Process Pla	ın: W	<u></u>	Date:		Tooling: SPC (Y/N):		Date:		1	Run	Start Stop		
Sequence ID/ Work Center II		Operation Description				Set Up/ Run Hours	Tool II	Tool#	Plan Code	Accept Qty	Reje Qty		Reject Number	Insp. Stamp
Draw Nbr D3446	Rev	vision Nbr B												
QC Quality Control			<b>Memo</b> INSPECT F SCRAP	RA111244		0.00	06/27		40					

110

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

Quality Control

11/6/28 AS

Page 1

#### **Picklist Print**

Monday, June 27, 2011 1:55:46 PM

Work Order ID:

71071

Parent Item:

D3446-13

Parent Item Name:

Right Buckle Harness

Start Date: 6/21/2011

Required Date: 6/22/2011

Start Qty: 1.00

Required Qty: 1.00

**Comments:** 

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3446-13		Manufactured	No		•		Each	0.0000		1			
Right Buckle Harness									1				

Right Buckle Harness

# RA 111244 D3446-13 B41001

Received at Dart Aerospace June 21, 2011 Inspected June 21, 2011

#### **Instructions for RA 111244**

- The white tag has been removed (ID tag)
- Rivet on retaining pin is broken
- Inform B.A.E System SCHROTH of issue and peruse a credit
- Belt otherwise is scrap

## DART Aerospace Ltd

### **CUSTOMER RETURN**

#RA:	111 244 <u> </u>
Date:	11-06-20

ator: Sino Willer	m5	-	Invoice #: SO#:
npany: Heliquest		- Attach Copy of D	HS Return Authorization #:
ne No.:	000	- #: PAR#: _	
#: NCR#	: CSR	#:	!
son for Return:			
See ottached.			/
aching: Ot 1	1	ERORO	Prepaid Collect
ceiving: te Received: ///c/2/	Freight Company:	tion -	Distribute to QC
Part #	Batch # Descrip	(IOH	Advise QA Date:
13776-13	B7/00/		
		2000	Photograph Required: yes / no
ondition of Packaging:		ARC Docs	Other Manual
C: uarantine Location:  spectors Initial:  Part # DayWar	Date: Wob 121  CHG # Batch #  HASH2	Photograph Required:  QC Comments  Shape  The the white they  (TD too)  Rown  Scrape	yes no  QC Approval Initial W/O# Scra  Remoco 10011
QA Coordinator: Advise GM as to Findings: Comments:	Initial:	Date: 11.06.2	
10000 01000 1 / /			Freight:
GM Approval:		ate: WDG. LI	Net Credit Customer

Copy of Customer Return to stay with work orders and another copy to be filed with customer credit